



instructables

---

## Volkswagen Transporter T5 Cup Holder Drinks Holder



by x8rltd

### The problem

The OEM Volkswagen cup holder works by retracting to & from the dashboard, when it pops out there are two flaps which hold two drinks. However the flaps work on a spring mechanism which often breaks. The flaps also put too much pressure on paper cups (such as those from drive-thrus) and can cause them to spill.

### Symptoms of the fault

Broken cup holder mechanism, spilling drinks, rattling cup holder

### Vehicles affected

Volkswagen Transporter T5 and T5.1 (2003-2016)

Including Caravelle and California

### *Associated part numbers*

7H2 858 601

7H2 857 321K

### Our solution

We have created an improved design cup holder insert which has been injection molded for precision and quality. The insert also makes it far easier to insert a drinks cup or bottle whilst driving

### You will receive

1 X ABS injection molded cup holder insert

### **Supplies:**

There are no tools needed to fit this part!





IMPROVED VEHICLE COMPONENTS



IMPROVED VEHICLE COMPONENTS



---

### **Step 1: Fit the Cup Holder**

Pull out the cup holder tray from the dashboard and insert the cup holder insert between the flaps. Even if one of the sides is broken you should still have the cup holder insert fitting firmly.





